





Part List

Part No.	Name	Material	Quantity
1	Casting	C.I.	1
2	Bearing	C.I.	1
3	Spindle	M.S.	1
4	Lock-nut	M.S.	1
5	Fork	Cast steel	1
6	Nut	M.S.	1
7	Set screw	M.S.	2
8	Set screw	M.S.	2
9	Disc	Brass	1
10	Disc	Brass	1
11	Set screw	M.S.	1
12	Bush	Brass	1

\*\*\*\*\*